

Hi Bob,

Hope your hot summer is not bothering you and you are cool inside. I am not making any great strides on the build but any progress is progress.



Pic #37 While rebuilding the Cadillac Northstar, I installed head studs into the block to keep the heads on tight.



Pic #38 I hope that I don't have any parts left over. It's easier to rebuild it now than later.



Pic #39 After dropping the brake booster 3/4" along with lowering the A/C accumulator, I mounted the windshield/door hinge support bar.



Pic #40 Picture shows bracing from hinge support area down to the front Fiero side frame area.



Pic #41 Picture shows the area where the upper body support tubing attaches to the left side of the windshield area.



Pic #42 This picture shows the upper cage tubing for strength of the chassis.



Pic #43 Picture shows a side view of body support framework.



Pic #44 Here we have a shot of the rear framework tubing.



Pic #45 Here are the taillights that I purchased from www.rallylights.com. They were very economical compared to OEM.



Pic #46 This is the backside view of the taillights. Thanks for posting - Jim C.