



Pic #7 Passenger compartment braced for major cut behind firewall



Pic #8 We have separation!!!



Pic #9 On checking my AGP glass...maybe I should make it a 4-door???  
NOTE: 1997 Diablo windshield was different than 2001 Diablo 6.0



Pic #10 Rear firewall cleaned up after removal of gas tank.